42-003-00032



United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

PECEIVED MAY 25 2011 3AP20

May 13, 2011

Mr. Ed Peresie Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Mr. Steve Hepler Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject:

USS Reference Number: 11-0110 Termination

ACHD Reference Number: 13719

400 Claus Plant USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

James F. Dudek Plant Manager Clairton Works

## NOTICE OF PLANNED OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

USS Reference Number: 11-0110 Termination 1.

ACHD Reference Number: 13719

Date & Time of Outage: Date: 04/28/11 Time: 0600 hours 2.

Company Name: U.S. Steel Corporation - USS Clairton Works 3.

Specific Equipment Involved or Affected: 400 Claus Plant 4.

- BAPC Permit Number (if applicable): 5.
- 6. Location: Clairton, PA
- Nature and cause of breakdown: During an approximate 3 week 7. period, the 400 Claus Plant will be unavailable for service to perform general maintenance.

The 400 Claus Unit is a redundant piece of equipment. Gas processing for sulfur removal was handed off to the 600 Claus Unit. Sulfur Plant performance will not be affected. Sulfur emissions will not increase.

- Identification of Emissions: 8.
  - Type(s) (CO, NOX, SO2, Particulates, Hydrocarbons, etc.) Α. The 600 Claus Plant will carry the full acid gas flow to the plant. No environmental impact is expected.
  - Toxic qualities of each type (including its qualities as an B. irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
  - Amount of each type emitted (or likely to be emitted). C. N/A
- Measures taken (or to be taken) to minimize length of breakdown 9. and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

Personnel, materials and equipment were on site prior to the start of the outage. The 600 Claus Plant carried the full acid gas flow to the plant.

Facility back in operation - Date: 05/09/11 Time: 1500 hours 10.

Signature 3 1 Date 5/13/11 Bryan M. Kresak

Environmental Control Engineer Phone: 412-233-1468